G28A Encounter Overview



Note: DSS-14 is unavailable until DOY 00-172 (June 20)

Note 2: Two Bus Reset PORs occurred during the encounter time period, both of which were properly handled by the on-board recovery routine. The times were: 00-142/02:45:19 SCET and 00-142/16:23:47 SCET.

BMcL/SST
05/22/00