OVERVIEW OF EJ-2 Part 1 of 2



Note: Spacecraft activities were interrupted on 93-191/20:16 SCET and 93-193/01:37 SCET by A-String CDS Bus Resets, which resulted in spacecraft safing.

BMcL
12/11/99