


OVERVIEW OF EJ-1 (Part 2 of 2)



Note: Spacecraft activities were interrupted on 93-161/16:53 SCET and on 93-168/18:22 SCET by A-String CDS Bus Resets which resulted in spacecraft safing. Sequence control was regained at the start of EJ-2 on 93-187/16:15 SCET.