


OVERVIEW OF EJ-2 Part 2 of 2



Note: Spacecraft activities were interrupted on 93-223/22:04 SCET by an A-String CDS Bus Reset, which resulted in spacecraft safing.