


# I27A Encounter Overview



Note: Two Bus Reset PORs occurred during the encounter time period, both of which were properly handled by the on-board recovery routine. The times were: 00-053/08:53:23 SCET and 00-054/00:45-01:45 SCET (indeterminate, MRO not received). Full safeing (due to simultaneous bus reset) occurred at 00-055/12:00:13 SCET.