


# EJ07B' OVERVIEW

(2/2)



SEQ 9/27/94  
BMcL 2/9/00

5 7 9 12 14 16 19 21 23 26 28 30 3 5 7 10 12 14 17 24  
 Sept Oct

Note: Activities in EJ-7B were interrupted by a DMSMRO memory failure, resulting in spacecraft safing at 94-257/03:10:51 SCET and a second safing at 94-259/16:38 SCET caused by a CAP privileged error.