


# I33B Sequence Overview - Part 1



Note: Spacecraft activities were halted at 02-017/13:41:10 SCET by spacecraft safing (Despun Bus Parity Error), and again at approximately 02-047/20:51 SCET by a spacecraft safing incident (A-String down).

SST/BMcL  
03/07/02